

Technical Journal

TITLE:

P3 AC system, unusual noise when AC compressor is running

| REF NO: TJ 29474 | ISSUING DEPARTMENT: Technical Service | CAR MARKET: United States and Canada | | |
|---------------------|---------------------------------------|--------------------------------------|-------------------------|--|
| 3 US 7510 V | PARTNER: olvo Cars North America | ISSUE DATE: 2015-09-21 | STATUS DATE: 2015-11-02 | |
| FUNC GROUP: 8743 | FUNC DESC: Compressor and mounting | Page | 1 of 2 | |

"Right first time in Time"

Attachment

Vehicle Type

| Type | Eng | Eng Desc | Sales | Body | Gear | Steer | Model Year | Plant | Chassis range | Struc Week Range |
|------|-----|-------------|-------|------|------|-------|------------|-------|---------------|---------------------|
| 1XX | 61 | | | | | | 2012-2013 | | - | 201046-201319 |
| 1XX | 61 | | | | | | 2014-2015 | | - | 201320-201426 |
| 1XX | 62 | | | | | | 2012-2013 | | - | 201046-201319 |
| 1XX | 90 | | | | | | 2012-2015 | | - | 201120-201426 |
| 1XX | 94 | | | | | | 2012-2015 | | - | 201120-201426 |
| 1XX | 95 | | | | | | 2012-2015 | | - | 201120-201426 |
| 1XX | A9 | | | | | | 2014-2015 | | - | 201320-201426 |

CSC Customer Symptom Codes

| Code | Description |
|------|--------------------------------------|
| D5 | Climate control system/Unusual noise |

VST Operation Number

| VST Operation Number | Description | | | |
|----------------------|--|--|--|--|
| 87456-2 | Replace hose/pipe side member-compressor | | | |
| 87004-2 | Refrigerant drain and fill | | | |

Technical Journal 29474



DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

Unusual noise described as a drilling noise may be audible from the AC system when the AC compressor is engaged, most frequent during idle or low speed driving and ambient temperature range 59-86 degrees.

PRODUCT MODIFICATION:

New AC pipe with integrated muffler has been introduced at the factories from 2014w26 for 5cyl and 6 cyl engines. New part number was added for -2013w20 5cyl engines and if this noise is present, do not replace the AC compressor or TXV valve.

Note:

This hose was introduced in the 4 cyl engine 2013w46.

VEHICLE REPORT:

When submitting a Vehicle Report for a condition described in this TJ, use concern area "Vehicle Report and sub concern area "Support Not Needed" with function group 8743.

SERVICE:

In case of customer complaints, install the new AC pipe with muffler according to VIDA.

P/N31436536 5cyl engines

P/N31407977 5cyl engines -2013w20

P/N31436537 6cyl engines

P/N31407976 5cyl engines Diesel

Page 2 of 2 2015-11-02